


[Main page](#) > [Cell Phone Parts](#) > [Electronic components](#) > [Apple](#) > [USB Charging IC - 68803 9 PIN \(tristar\)](#)



## USB Charging IC - 68803 9 PIN (tristar)

---

Product ID: 21954

Price: **7.00 EUR**

---

Product weight: **0.01 kg**

### Description:

USB Charging IC - 68803 9 PIN (tristar) is a BGA chip that communicates with the charger before it can charge the phone and often causes slow or no charge. Damaged most often when connected to an original Apple charger. The 68803 is described in the iPhone 4, iPad 2 and as U2

#### Contact details:

Telefon: +48 17 227 00 25  
Infolinia: 0 801 671 717  
E-mail: [biuro@multi-com.pl](mailto:biuro@multi-com.pl)  
Skype: Multi-COM

#### Address:

Multi-COM Sp. z o.o.  
ul. Stanisława Krzaklewskiego 31b  
36-100 Kolbuszowa  
POLSKA

[Go to the product](#)

