

Main page > Mobile Phone Repair Services > Bootloader repair > HTC > Bootloader repair HTC Diamond



## Bootloader repair HTC Diamond

---

Product ID: 8930

Price: **30.00 EUR**

---

Product weight: **0.40 kg**

### Description:

Bootloader repair HTC Diamond it's service that allows repair your damaged phones after unsuccessful firmware upgrade/downgrade. Repair are make using our JTAG JIGs so we don't solder in phones (exception are phones that using Molex port connector - then this connector are installed as same as in any authorized service point).

### Contact details:

Telefon: +48 17 227 00 25

Infolinia: 0 801 671 717

E-mail: [biuro@multi-com.pl](mailto:biuro@multi-com.pl)

Skype: Multi-COM

### Address:

Multi-COM Sp. z o.o.

ul. Stanisława Krzaklewskiego 31b

36-100 Kolbuszowa

POLSKA

[Go to the product](#)

