

Main page > Mobile Phone Repair Services > Bootloader repair > LG > Bootloader repair LG P710 (Optimus L7 II)



## Bootloader repair LG P710 (Optimus L7 II)

---

Product ID: 14367

Price: **30.00 EUR**

---

Product weight: **0.40 kg**

### Description:

Bootloader repair LG P710 (Optimus L7 II) it's service that allows repair your damaged phones after unsuccessful firmware upgrade/downgrade. Repair are make using our JTAG JIGs so we don't solder in phones (exception are phones that using Molex port connector - then this connector are installed as same as in any authorized service point).

#### Contact details:

Telefon: +48 17 227 00 25  
Infolinia: 0 801 671 717  
E-mail: [biuro@multi-com.pl](mailto:biuro@multi-com.pl)  
Skype: Multi-COM

#### Address:

Multi-COM Sp. z o.o.  
ul. Stanisława Krzaklewskiego 31b  
36-100 Kolbuszowa  
POLSKA

[Go to the product](#)

