

Main page > Mobile Phone Repair Services > Bootloader repair > Samsung > Bootloader repair Samsung M8800 (Pixon)



Bootloader repair Samsung M8800 (Pixon)

Product ID: 9176

Price: **30.00 EUR**

Product weight: **0.40 kg**

Description:

Bootloader repair Samsung M8800 (Pixon) it's service that allows repair your damaged phones after unsuccessful firmware upgrade/downgrade. Repair are make using our JTAG JIGs so we don't solder in phones (exception are phones that using Molex port connector - then this connector are installed as same as in any authorized service point).

Contact details:

Telefon: +48 17 227 00 25
Infolinia: 0 801 671 717
E-mail: biuro@multi-com.pl
Skype: Multi-COM

Address:

Multi-COM Sp. z o.o.
ul. Stanisława Krzaklewskiego 31b
36-100 Kolbuszowa
POLSKA

[Go to the product](#)

