


Main page > Cell Phone Parts > Electronic components > Apple > USB Charging IC - NXP 1610A2 U1700/U3500 (tristar)



## USB Charging IC - NXP 1610A2 U1700/U3500 (tristar)

---

Product ID: 21952

Price: **7.00 EUR**

---

Product weight: **0.01 kg**

### Description:

USB Charging IC - NXP 1610A2 U1700/U3500 (tristar) is a BGA chip that communicates with the charger before it can charge the phone and often causes slow or no charge. Damaged most often when connected to an original APple charger. The NXP 1610A2 is described in the iPhone 6/6+ as U1700 and iPad Air 2 as U3500

#### Contact details:

Telefon: +48 17 227 00 25  
Infolinia: 0 801 671 717  
E-mail: [biuro@multi-com.pl](mailto:biuro@multi-com.pl)  
Skype: Multi-COM

#### Address:

Multi-COM Sp. z o.o.  
ul. Stanisława Krzaklewskiego 31b  
36-100 Kolbuszowa  
POLSKA

[Go to the product](#)

